

# BELARC ADVISOR

## PC AUDITS IN YOUR WEB BROWSER!

The license associated with the Belarc Advisor product allows for **free personal use only**. Use on multiple computers in a corporate, educational, military or government installation is prohibited. See the [license agreement](#) for details. The information on this page was created locally on your computer by the Belarc Advisor. Your computer profile was not sent to a web server. [Click here for more info.](#)

### [About Belarc](#)

### [System Management Products](#)

### [Your Privacy](#)

## Computer Profile Summary

*Computer Name:* Owner-b0c033318 (in WORKGROUP)

*Profile Date:* Tuesday, April 07, 2009 10:48:34 AM

*Advisor Version:* 7.2t

*Windows Logon:* Owner

**[Click here for Belarc's System Management products, for large and small companies.](#)**

### In page Links:

#### [Installed Hotfixes](#)

#### [Software Licenses](#)

#### [Software Versions](#)

### Operating System

Windows XP Professional Service Pack 2 (build 2600)

### System Model

Dell Inc. Inspiron 2200

System Service Tag: [3VHLM81 \(support for this PC\)](#)

Chassis Serial Number: 3VHLM81

Enclosure Type: Portable

### Processor <sup>a</sup>

600 megahertz Intel Pentium M  
64 kilobyte primary memory cache  
2048 kilobyte secondary memory cache

### Main Circuit Board <sup>b</sup>

Board: Dell Inc. 0U6962

Serial Number: .3VHLM81.CN486435961750.

Bus Clock: 133 megahertz

BIOS: Dell Inc. A07 12/01/2005

### Drives

60.00 Gigabytes Usable Hard Drive Capacity  
55.85 Gigabytes Hard Drive Free Space

HL-DT-ST CDRW/DVD GCC4244 [CD-ROM drive]

USB Flash Memory USB Device [Hard drive] (2.01 GB) -- drive 1

WL60GLPA854 [Hard drive] (60.01 GB) -- drive 0, s/n LP29507, rev 09.07D09, [SMART](#) Status: Healthy

### Memory Modules <sup>c,d</sup>

504 Megabytes Installed Memory

Slot 'System Board Memory' has 256 MB  
Slot 'DIMM\_B' has 256 MB (serial number C1871A91)

### Local Drive Volumes

c: (NTFS on drive 0)	60.00 GB	55.85 GB free
----------------------	----------	---------------


### Network Drives

*None detected*

### Users (mouse over user name for details)

local user accounts	last logon
Owner	4/7/2009 10:35:48(admin) AM

local system accounts		
Administrator	never	(admin)
✘ Guest	never	
✘ HelpAssistant	never	
✘ SUPPORT_388945a0	never	

✘ Marks a disabled account;  Marks a locked account

### Printers

*None detected*

**Controllers**

Intel(R) 82801FB/FBM Ultra ATA Storage  
Controllers - 266F  
Primary IDE Channel [Controller]

**Bus Adapters**

Texas Instruments PCI-1510 CardBus Controller  
Intel(R) 82801FB/FBM USB Universal Host  
Controller - 2658  
Intel(R) 82801FB/FBM USB Universal Host  
Controller - 2659  
Intel(R) 82801FB/FBM USB Universal Host  
Controller - 265A  
Intel(R) 82801FB/FBM USB Universal Host  
Controller - 265B  
Intel(R) 82801FB/FBM USB2 Enhanced Host  
Controller - 265C

**Communications**

Conexant D110 MDC V.92 Modem

Dell Wireless 1370 WLAN Mini-PCI Card  
**primary** Auto IP Address: 192.168.1.6 / 24  
Gateway: 192.168.1.1  
Dhcp Server: 192.168.1.1  
Physical Address: 00:14:A4:23:3A:6C

Intel(R) PRO/100 VE Network Connection  
Physical Address: 00:14:22:B5:B3:7C

Networking Dns Server: 192.168.1.1

**Virus Protection** [[Back to Top](#)]

**avast! antivirus 4.8.1169 [VPS 090407-0]**

Version 4.8.1169

Realtime File Scanning On

**Missing Microsoft Security Hotfixes** [[Back to Top](#)]

*No details available*

**Installed Microsoft Hotfixes** [[Back to Top](#)]**Internet Explorer**

SP2

(SP2)

**Windows Media Player**

KB952069\_WM9

([details...](#))

SP0

✓ KB952069\_WM9 on 4/7/2009

([details...](#))

**Windows XP**

SP3

✓ KB839210 on 10/18/2007 ([details...](#))

✓ KB898461 on 4/5/2009 ([details...](#))

✓ KB912812 on 10/18/2007 ([details...](#))

✓ KB944338-V2 on 4/7/2009 ([details...](#))

SP4

✓ KB938464-V2 on 4/7/2009 ([details...](#))

✓ KB946648 on 4/7/2009 ([details...](#))

✓ KB950760 on 4/7/2009 ([details...](#))

✓ KB950762 on 4/7/2009 ([details...](#))

✓ KB950974 on 4/7/2009 ([details...](#))

✓ KB951066 on 4/7/2009 ([details...](#))

**Display**

Mobile Intel(R) 915GM/GMS,910GML  
Express Chipset Family [Display adapter] (2x)  
QDS 14.9 [Monitor] (14.9"vis) (3x)

**Multimedia**

SigmaTel C-Major Audio

**Other Devices**

Microsoft AC Adapter  
Microsoft ACPI-Compliant Control Method  
Battery  
Standard 101/102-Key or Microsoft Natural  
PS/2 Keyboard  
PS/2 Compatible Mouse  
USB Mass Storage Device  
USB Root Hub (5x)

- ✓ KB951376-V2 on 4/7/2009 ([details...](#)) ✓ KB967715 on 4/7/2009 ([details...](#))  
 ✓ KB951698 on 4/7/2009 ([details...](#))

**[Click here](#) to see all available Microsoft security hotfixes for this computer.**

- ✓ Marks a HotFix that verifies correctly  
 ✗ Marks a HotFix that fails verification  
 (note that failing hotfixes need to be reinstalled)  
 Unmarked HotFixes lack the data to allow verification

**[Click here for Belarc's System Management products,](#)  
[for large and small companies.](#)**

#### Software Licenses [\[Back to Top\]](#)

Belarc - Advisor	5fa80026
Dell Computer - SysInfo	D2R0981
Microsoft - Internet Explorer	76487-OEM-0011903-00102 (Key: XJM6Q-BQ8HW-T6DFB-Y934T-YD4YT) <sup>e</sup>
Microsoft - WebFldrs XP	12345-111-11111111-87099
Microsoft - Windows XP Professional	76487-OEM-0011903-00102 (Key: XJM6Q-BQ8HW-T6DFB-Y934T-YD4YT) <sup>e</sup>

#### Software Versions (mouse over \* for details, click \* for location) [\[Back to Top\]](#)

ALWIL Software - avast! Antivirus Version 4, 8, 0, 0 *	Microsoft Corporation - Internet Explorer Version 6.00.2900.2180 *
Belarc, Inc. - Advisor Version 7.2t *	Microsoft Corporation - Messenger Version 4.7.3000 *
Cinematronics - 3D Pinball Version 5.1.2600.2180 *	Microsoft Corporation - Windows Installer - Unicode Version 3.0.3790.2180 *
Create and edit drawings, flow charts, and logos by using Draw. *	Microsoft Corporation - Windows Movie Maker Version 2.1.4026.0 *
Create and edit presentations for slideshows, meeting and Web pages by using Impress. *	Microsoft Corporation - Windows® NetMeeting® Version 3.01 *
Create and edit scientific formulas and equations by using Math. *	Microsoft Corporation - Zone.com Version 1.2.626.1 *
Create and edit text and graphics in letters, reports, documents and Web pages by using Writer. *	Microsoft Data Access Components Version 3.525.1117.0 *
Cyberlink PowerCinema 3.0 Version 3.00.0000 *	Microsoft(R) Windows Media Player Version 9.00.00.3250 *
Cyberlink PowerDVD 5.0 Version 5.00.0000 *	OpenOffice.org 2.2 Version 1.09.9129 *
Dell Wireless WLAN Card Wireless Network Tray Applet Version 4.10.47.3 *	Perform calculation, analyze information and manage lists in spreadsheets by using Calc. *
Dell Wireless WLAN Tray Service *	Roxio - DirectCD Version 5.3.4.21 *
Intel(R) Common User Interface Version 7.0.0.4609 *	Roxio - Easy CD Creator Version 5.3.4.21 *
Manage databases, create queries and reports to track and manage your information by using Base. *	Sun Microsystems, Inc. - Java(TM) Platform SE 6 U13 Version 6.0.130.3 *
Microsoft (r) Windows Script Host Version 5.6.0.8820 *	unopkg.exe *

\* Click to see where software is installed.

- Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot

contents are wrong.

e. This may be the manufacturer's factory installed product key rather than yours.

Copyright 2000-7, Belarc, Inc. All rights reserved.

[Legal notice](#). U.S. Patents 6085229, 5665951 and Patents pending.

---